

Our Ref: SW/LS/BR

05 February 2019

Report 336302

Page 1 of 2

SMD Contracts Limited Unit F2 Pittman Way Fulwood Preston PR2 9ZD

Contact: Katie Hamblett

:

:

:

:

DATE RECEIVED REPUTED FIBRE CONTENT FABRIC DESCRITION COLOUR/DESIGN BATCH NUMBER 18 JANUARY 2019 NOT GIVEN WOVEN BRODIE CONTRACTS 134 UK TESTING

REQUEST: Flammability in accordance with IMO 2010 FTP CODE ANNEX 1 PART 8

COMMENTS: See report

S. WISEMAN LABORATORY DIRECTOR

l Sheridan

L. SHERIDAN LABORATORY MANAGER

This report shall not be reproduced except in full without written approval of HSTTS. In all circumstances results of tests are implied as referring only to the sample supplied and should not be construed or interpreted on any other basis. The comments given in the report are for guidance only and are not a part of the results. Where specified in a test method preconditioning in accordance with ISO 139 is not carried out as samples are exposed to the conditioning atmosphere specified within ISO 139 for a minimum of 16 hours prior to test.

*This test has been sub-contracted



Our Ref: SW/LS/BR

Report 336302

05 February 2019

Page 2 of 2

Flammability in accordance with IMO 2010 FTP CODE ANNEX 1 PART 8

Conditioning

A minimum of 96 hour at 50±5% relative Humidity, 23±2°C

Report

The following test results relate to the behaviour of the test specimens of a product under the particular conditions of the test; they are not intended to be the sole criterion for assessing the potential fire hazard of the product in use.

Ignition Source	Observations	Result
Smouldering	No flaming or progressive smouldering was observed within one hour of	Pass
cigarette	placement of the cigarettes.	
Propane flame	No flaming or progressive smouldering was observed after removal of	Pass
	the propane flame.	

Note: A 20-22 kg/m³ non-fire retardant polyurethane foam was used as the filling.